

Insulation resistance tests

HIOKI

Contents

Photo/Drawing with Values	1 / 3
Photo/Drawing with Values Image	3 / 3

Photo/Drawing with Values

Date	Time	Title
2018-11-13	14:08:15	Switchboard

Measurement Location	Measured by	Witnessed by
動力盤 3		

1. Measurement Results

No.	Date	Time	Measured value		Function	Mode	Status	Filter	Instrument Name	Comment
1	2018-11-13	14:03:16	> 50.0	MΩ			250V RANGE		IR4054#000000015	
2	2018-11-13	14:03:24	> 50.0	MΩ			250V RANGE		IR4054#000000015	
3	2018-11-13	14:03:39	> 50.0	MΩ			250V RANGE		IR4054#000000015	
4	2018-11-13	14:03:42	> 50.0	MΩ			250V RANGE		IR4054#000000015	
5	2018-11-13	14:03:45	> 50.0	MΩ			250V RANGE		IR4054#000000015	
6	2018-11-13	14:03:49	> 50.0	MΩ			250V RANGE		IR4054#000000015	
7	2018-11-13	14:03:51	> 50.0	MΩ			250V RANGE		IR4054#000000015	
8	2018-11-13	14:03:55	> 50.0	MΩ			250V RANGE		IR4054#000000015	
9	2018-11-13	14:03:58	> 50.0	MΩ			250V RANGE		IR4054#000000015	
10	2018-11-13	14:04:00	> 50.0	MΩ			250V RANGE		IR4054#000000015	
11	2018-11-13	14:04:03	> 50.0	MΩ			250V RANGE		IR4054#000000015	
12	2018-11-13	14:04:07	> 50.0	MΩ			250V RANGE		IR4054#000000015	
13	2018-11-13	14:04:09	> 50.0	MΩ			250V RANGE		IR4054#000000015	
14	2018-11-13	14:04:12	> 50.0	MΩ			250V RANGE		IR4054#000000015	
15	2018-11-13	14:07:43	0.015	MΩ			250V RANGE		IR4054#000000015	

Measured Value/Photo



Photo/Drawing with Values Image

Date	Time	Title
2018-11-13	14:08:15	Switchboard

1. Photo/Drawing with Values Image

